



HERITAGE TREE PROTECTION KEY

- TPZ 10X DIAMETER (AT NEW BUILDINGS)
- TPZ 8X DIAMETER (AT NEW DRIVEWAYS)
- TPZ 6X DIAMETER (AT NEW SITE WALLS)
- EXISTING HARDSCAPE / PAVING
- NEW/ REPLACEMENT HARDSCAPE / PAVING

NOTE: TPZ AS PER ARBORIST REPORT BY URBAN TREE MANAGEMENT DATED 08/2022;
VERIFY W/ TOWN ARBORIST

TREE SURVEY DATA

TAG NO.	COMMON NAME	DIAMETER AT BREAST HEIGHT	H/W	HEALTH	STRUCTURE	PROTECTED D.I.	TREE DISPOSITION	NOTES, RECOMMENDATIONS
1	Coast redwood	16.9	47/12'	fg	fg	x	B	DWR, EWR
2	Valley oak	27.6	40/28'	fg	fg	x	C	CD at 15'; DWR, EWR, cable, RCE
3	Coast redwood	32.7	75/23'	fg	fg	x	B	DWR, EWR
4	Coast redwood	35.4	85/32'	fg	fg	x	B	DWR, EWR
5	Coast redwood	33.5	82/28'	fg	fg	x	B	DWR, EWR
6	Coast redwood	28.2	77/25'	fg	fg	x	B	DWR, EWR
7	Coast redwood	32.3	76/20'	f	fg	x	B	DWR, EWR, partially shaded out by adjacent redwoods
8	Coast redwood	32.7	72/28'	fg	fg	x	B	DWR, EWR
9	Coast redwood	24.4	45/20'	fg	fg	x	B	DWR, EWR
10	Coast redwood	22.8	55/25'	f	fg	x	B	DWR, EWR, partially shaded out by adjacent trees
11	California bay	35.3 x 1.5	55/25'	fg	fg	x	C	CD at 2'; DWR, EWR, unbalanced canopy
12	Coast redwood	30.3	72/28'	fg	fg	x	B	DWR, EWR
13	Coast redwood	41.7	72/25'	fg	fg	x	B	DWR, EWR, dominating adjacent small redwood
14	Coast redwood	16.6	45/17'	fg	f	x	C	Growing directly into dominant redwood canopy, limb breakage issues imminent, RR
15	Valley oak	32.7	45/30'	fg	fg	x	C	CD at 5.5'; RCE, cable, DWR, EWR
16	Coast redwood	61.6	100/45'	f	fg	x	B	CD at 7'; Cable, some grilling roots, DWR, EWR
17	Coast redwood	51.2	85/35'	fg	fg	x	B	DWR, EWR, some small grilling roots
18	Coast redwood	61.3	95/28'	f	fg	x	B	DWR, EWR
19	Coast live oak	22	45/20'	fg	fg	x	C	CD at 25'; heavy lean towards street, DWR, EWR, growing against fence, RCE
20	Coast live oak	18.9	55/20'	f	fg	x	C	Growing through fence, leaning over flag lot driveway, DWR, EWR, bacterial ooze at 15'
21	Coast live oak	34.7	55/20'	f	fg	x	B	Outside fence on flag lot driveway, CD at 6'; RCE, DWR, EWR, cable
22	Coast live oak	34.7	55/20'	f	fg	x	B	Outside fence on flag lot driveway, CD at 6'; RCE, DWR, EWR, cable
A = Retain, condition warrants long-term preservation B = Preserve, tree is a benefit and may be worthy of extensive effort or design accommodation. C = May be preservable but is not worthy of extensive effort or design accommodation. D = Recommend removal due to existing condition and/or structure								
TOTAL TREES								
Total Protected Trees								